



Drawing Number	Rev #	Ship Mark	Piece Mark	Quantity	Size of Material	Grade	Length	Finish	Notes
RF38	0	RF38	RF38	2	HSS10X10X.250	A500-B	4'-5 3/16"		
RF38	0		p20	2	HSS10X10X.250	A500-B	1'-2"		
RF38	0		p21	2	HSS10X10X.250	A500-B	0'-4"		
RF38	0		p22	2	PLT38X16	A36	2'-0 1/8"		
RF38	0		p24	4	PLT38X12	A36	1'-8 1/8"		
RF38	0		p25	4	PLT38X12	A36	2'-7 1/4"		
RF38	0		p26	4	PLT38X4 7/16	A36	1'-1 7/16"		
RF38	0		p27	2	HSS6X6X.250	A500-B	0'-6"		
RF38	0		p28	4	PLT14X9 1/2	A36	0'-9 1/2"		
RF38	0		p29	8	PLT14X5 5/8	A36	0'-9 1/2"		
RF38	0		p36	4	PLT38X9 1/4	A36	1'-2 3/16"		
RF38	0		p71	4	L3X3X1/4	A36	0'-8 1/2"		
RF38	0		p138	2	PLT14X22 5/8	A36	2'-0 1/16"		
RF38	0		p139	4	FB38X4 1/2	A36	1'-2 5/16"		
RF38	0		r22	4	HSS14X10X.375	A500-B	32'-7 3/8"		
RF38	0		r24	4	HSS14X10X.375	A500-B	22'-10 9/16"		
RF38	0		r21	72	NELSON-STUD-5/8-DIA	A307	0'-2 1/2"		

2 ASSEMBLIES REQUIRED AS DRAWN